


Nut-Fast

Flat Head Hexagonal Rivet Nuts

Material

Low Carbon Steel 1008/1010



M4x0,7

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,2	ØD2 ±0,3	k ±0,2	
TF1144-04-10120N	0,5-2,0	11,0	6,0	6,0	9,0	0,8	1.500

M5x0,8

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,2	ØD2 ±0,3	k ±0,2	
TF1144-05-10125N	0,5-2,5	14,0	7,0	7,0	10,0	1,0	1.000

M6x1,0

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,2	ØD2 ±0,3	k ±0,2	
TF1144-06-10130N	0,5-3,0	16,0	9,0	9,0	13,0	1,5	3.000

M8x1,25

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,2	ØD2 ±0,3	k ±0,2	
TF1144-08-10135N	0,5-3,5	18,0	11,0	11,0	16,0	1,5	2.000

M10x1,5

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,2	ØD2 ±0,3	k ±0,2	
TF1144-10-10135N	0,5-3,5	21,0	13,0	13,0	17,0	1,7	1.000

M12x1,75

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,2	ØD2 ±0,3	k ±0,2	
TF1144-12-10140N	0,5-4,0	24,0	15,0	15,0	19,0	1,9	1.000