


Nut-Fast

Flat Head Hexagonal Rivet Nuts Closed

Material

Low Carbon Steel 1008



M4x0,7

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,3 -0,2	ØD2 ±0,3	k ±0,2	
TF1144-04-10120-C	0,5-2,0	17,3	6,0	6,0	9,0	0,8	1.000

M5x0,8

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,3 -0,2	ØD2 ±0,3	k ±0,2	
TF1144-05-10125-C	0,5-2,5	19,5	7,0	7,0	10,0	1,0	1.000

M6x1,0

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,3 -0,2	ØD2 ±0,3	k ±0,2	
TF1144-06-10130-C	0,5-3,0	24,3	9,0	9,0	13,0	1,5	500

M8x1,25

PART #		L ±0,3	SW1 +0,1 -0,0	SW -0,3 -0,2	ØD2 ±0,3	k ±0,2	
TF1144-08-10135C	0,5-3,5	28,0	11,0	11,0	15,0	1,5	250